

AlliedWare™ and AlliedWare Plus™ OS

Overview of | Minimum Requirements for 100MB Fibre SFP Support

Product	Hardware revision	Software version
AT-9924SP	Board revision: M4 Order as: AT-9924SP-V2-xx (990-002215-xx) AT-9924SP-DP-V2-xx (990-002214-xx)	2.9.1 and higher
AT-8948	not supported	not supported
AT-9924T	not supported	not supported
AT-9924T/4SP	not supported	not supported
x900-48FS	all	291-08 and higher
x900-24XS	all	3.2.1 and higher 5.2.1 and higher
x900-12XT/S	all	first customer version
SwitchBlade x908	all	5.2.1 and higher
AR770S	all	291-04 and higher
SwitchBlade 4000 (AT-SB4442 V2 card)	not supported	not supported
XEM-12S	all	3.2.1 and higher 5.2.1 and higher
AT-A61	not supported	not supported

USA Headquarters | 19800 North Creek Parkway | Suite 200 | Bothell | WA 98011 | USA | T: +1 800 424 4284 | F: +1 425 481 3895
 European Headquarters | Via Motta 24 | 6830 Chiasso | Switzerland | T: +41 91 69769.00 | F: +41 91 69769.11
 Asia-Pacific Headquarters | 11 Tai Seng Link | Singapore | 534182 | T: +65 6383 3832 | F: +65 6383 3830
www.alliedtelesis.com

© 2007 Allied Telesis, Inc. All rights reserved. Information in this document is subject to change without notice. Allied Telesis is a trademark or registered trademark of Allied Telesis, Inc. in the United States and other countries. All company names, logos, and product designs that are trademarks or registered trademarks are the property of their respective owners.